

E³ SolidWorks Set-Up (User)

Start-Up Settings

Open SolidWorks

Double Click on SW Icon

Pop-Up: “License Agreement”

Select “Accept”

Pop-Up: “Welcome to SolidWorks”

Check “Do Not Show Me Any Dynamic Help”

Select “Ok”

General System Settings

Set File Menu

Expand “File” Menu and Pin Open

Hide Toolbars

Select View/Toolbars

Uncheck Motion Manager

Select View/Toolbars

Uncheck Task Pane

Load SW Settings File

Select Tools/Save Restore SW Settings

Select “Restore Settings”

Select “Next”

Browse to Desktop

Select “swSettings.sldreg”

Select “Open”

Select “Next”

Uncheck “Create Backup...”

Select “Finish”

Pop-Up: “SolidWorks Copy Settings Wizard”

Select “Yes”

Pop-Up: “SolidWorks Copy Settings Wizard”

Select “Ok”

General Document Settings

Turn Off Instant 3D

Open New Part

De-Select Instant 3D (Features Tab on Command Manager Menu)

Hide Command Manager

Select View/Toolbars/Customize

Under “Toolbars”

Uncheck “Enable Command Manager”

Select “Ok”

Close Part (X in far upper right corner/Don't Save)